

State of road surface is poor and poses risk to cyclists



Cycle road markings almost completely worn off and impossible to see, especially motor vehicle drivers



Motor vehicles move to centre of road to straddle the speed bumps:
on both the two way and one way / cycle contraflow sections



Motor vehicles move to centre of road to straddle the speed bumps:
Both the two way and one way / cycle contraflow sections



Cycle contraflow signs high and difficult to spot,
Tree position occludes left hand sign from view



Narrowing of road leaves little room for contraflow cycles and oncoming traffic
Double bend in road forces all traffic into centre, with risk to oncoming contraflow cyclists



Narrowing of road leaves little room for contraflow cycles and oncoming traffic



View when looking right at junction with Liverpool Road – angle of road, parked cars and pole make it challenging to see oncoming traffic especially when traffic approaching at speed

